

CLASSIFIED MESSAGE

DATE : 0015Z 16 MAR 58

TOP SECRET
SECRET

ROUTING

1		4	
2		5	
3		6	

TO : DIRECTOR

FROM : [REDACTED] 25X1A

ACTION: OPS (1-2)

INFO : S/C (3)

JHP

25X1A

2318Z 15 MAR 58

OPERATIONAL IMMEDIATE

25X1A

TO: [REDACTED]

PRECEDENCE

CITE: [REDACTED]

25X1A

25X1A

25X1A

REF: [REDACTED] (OUT 75255)

1. SYSTEM POWER SUPPLY INCURRED MAJOR FAILURE IN NEGATIVE 650 VOLTS DURING LAB PREFLIGHT. SYSTEM PROTOTYPE SUPPLY WAS HASTILY MODIFIED FOR MISSION. UNCERTAIN OF ITS RELIABILITY IN FLIGHT.
2. ELEVEN BOX PULLEY BELT FAILED AFTER 2 HOURS.
3. 10A BOX MAGAZINE JAMMED AFTER 100 FEET.
4. ALL OTHER UNITS OPERATED SATISFACTORILY.
5. SUMMARY OF SYSTEM PERFORMANCE ENCLOSED WITH MISSION TAKE.
6. SYSTEM 1. WILL BE OPERATIONAL WITHIN ITS NORMAL TURN AROUND TIME. [REDACTED] (IN 36162)).

25X1A

END OF MESSAGE

TOP SECRET
SECRET